

**IN THE SPECIFICATION:**

**Please amend paragraph [0065] as follows:**

Specifically, the transmission case 50 includes the ~~output shaft housing~~ output-shaft receiving section 54 on the centerline CL, and motor reception sections 56 are formed integrally with left and right side portions of the ~~output shaft reception~~ output-shaft receiving section 54. The motor reception sections 56 have left and right open sides that are closed with motor case halves 151 bolted to the reception section 56, and left and right transmission covers 152 are bolted to the motor case halves 151 to cover to respective motor case halves 151.